

EXHIBIT 22B

SAMPLE LABORATORY LASER STANDARD OPERATING PROCEDURES (SOP)

1. All personnel operating any laser in the laser lab must be certified and enrolled in the Naval Air Warfare Center Aircraft Division Lakehurst's Medical Surveillance Program.
2. Only the two electrical outlets connected to the emergency shut off switch shall be used for laser operation.
3. There shall be at least two people present when any work is being done with the lasers.
4. Laser personnel shall remove or cover all specular reflectors from the laser room.
5. Laser personnel shall remove all jewelry, (watches, rings, etc.), when working in the laser lab.
6. Laser personnel shall use the appropriate laser eyewear when working with the lasers.
7. Laser personnel must record all laser firings for review by the LSSO (Laser Safety Officer).

SAF-TM-5100

THIS PAGE INTENTIONALLY LEFT BLANK